NRC FORM 591M PART 1 (10-2003)				U.S. NUCLEAR REGULATORY COMMISSION			
10 CFR 2.201	SAFETY INS	PECTION REPORT	A۱	ND COMPLIANCE IN	ISPECTION		
LICENSEE/LOCATION INSPECTED:     Mechanical Integrity Solutions     Doral Bank Plaza, 33 Resolution Street, 4 <sup>th</sup> Floor     San Juan, Puerto Rico 00920				2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road			
REPORT Nos 2007002			King of Prussia, Pennsylvania 19406-1415				
3. DOCKET NUMBER( 03036190 LICENSEE:		4. LICENSE NUMBER( 52-25615-01	S)		5. DATE(S) OF INSPEC	TION	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:  1. Based on the inspection findings, no violations were identified.  2. Previous violation(s) closed.  3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.  Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):							
		,i					
4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  1) 49 CFR 172.202 REQUIRES THAT SHIPPING PAPELS INCLUDE THE PROPER UN NUMBER AND ASSOCIATED SHIPPING NAME. THE LICENSE'S UN NUMBER AND SHIPPING PAPELS (ONTAINED AN OUTDATED UN NUMBER AND SHIPPING NAME (UN 2974). PAPELS TO BE THANGED PROOF TO FULTHER SHIPMENT.  2) 10 CFR 34.79 REQUIRES THAT RECORDS OF ANNUAL RADIO GRAPHY RETAINED BE RETAINED FOR THREE YEARS. LICENSE COULD NOT PRODUCE RECORDS. FOR THREE PRODUCE WITH TRAINING LAST							
PRODUC	LE KECORDS   M = ATED   M DOCUMENTED: .	2005 TRAIN	1	ive Actions for Item	ULTED WITHIN		
corrective actions is ma	de in accordance with the ce will be achieved). I un	escribed by me to the insp e requirements of 10 CFR	ect 2.2	or will be taken to correct 201 (corrective steps alrea en response to NRC will b	4, above. the violations identified. Tady taken, corrective steps e required, unless specific gnature	which will be taken	
LICENSEE'S REPRESENTATIVE	Hector	R. Loza	N	1 /15	Mnil	-12/3/07	
NRC INSPECTOR	Ja	mes Schmidt		and	Schurt	12/3/07	
NRC FORM 591M PAR	T 1 (Rev. by RI 07/06)			G:\Docs\current\Insp Re	ecord\R 52-25615-01.2007	002.591MPart1.wpd	

SUNSI Review Completed By: /RA/ James Schmidt X Public